Capital Reserve Study 2018

Mariner's Cove Association

800 Lunalilo Home Road Honolulu, Hawaii 96825





1165 Bethel St., 2nd Floor Honolulu, Hawaii 96813 Phone: 808-539-9777 Fax: 808-521-2714

www.hawaiianprop.com

Mariner's Cove Association

Honolulu, Hawaii

RA Current Assessment Funding Model Summary

Report Date Account Number	September 25, 2017 951
Budget Year Beginning Budget Year Ending	January 01, 2018 December 31, 2018
Total Units	410

Report Parameters	
Inflation	2.00%
Annual Assessment Increase	0.00%
Interest Rate on Reserve Deposit	0.50%
Tax Rate on Interest	4.71%
Contingency	5.00%
2018 Beginning Balance	\$303,105.00

Project Summary

A Reserve Study was prepared using the cash flow method of analysis for the fiscal year.

This funding plan provides for fully funded reserve fund balances and complies with HRS 514B-148, approved by the association's Board of Directors as part of the new Budget.

It is important to recognize that a reserve study is a financial forecast of future funds required to maintain the capital components of the project. Hawaii law requires directors of the association to use reasonable efforts to project inflation, interest income, component inventory, component life & remaining life, and replacement costs of the project's components for a 20 year period. From this information, reserve contributions are calculated to fund the statutory replacement reserves. By its nature, a Reserve Study is an estimate to be used for annual budgeting purposes. The Reserve Study is a requirement of HRS 514A-83.6 and HRS 514B-148. The reserve study is not an audit or quality inspection of the project.

This Reserve Study has adopted a funding plan based on the cash flow method that provides full funding. The Reserve Study reflects that the Association is fully funded and has complied with the reserve requirements of Hawaii State Law; provided however, the association implements the funding plan and the criteria used reflects the project's actual operating experience during the life of the funding plan.

Current Assessment Funding Model Summary of Catcal	uuions
Required Biannually Contribution	\$16,836.00
\$41.06 per unit biannually	
Average Net Biannually Interest Earned	\$520.34
Total Biannually Allocation to Reserves	\$17,356.34
\$42.33 per unit biannually	


Current Assessment Funding Model Summary of Calculations

Mariner's Cove Association RA Current Assessment Funding Model Projection

Beginning Balance: \$303,105

J				Projected	Fully	
	Annual	Annual	Annual	Ending	Funded	Percent
Year	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
2018	33,672	1,041	110,187	227,631	349,446	65%
2019	33,672	1,009	41,322	220,990	349,875	63%
2020	33,672	1,106	14,448	241,320	379,345	63%
2021	33,672	1,136	28,316	247,812	394,976	62%
2022	33,672	1,144	33,239	249,389	406,248	61%
2023	33,672	1,064	51,594	232,531	399,411	58%
2024	33,672	1,022	43,502	223,724	402,083	55%
2025	33,672	1,146	8,664	249,878	441,813	56%
2026	33,672	1,254	12,261	272,543	478,204	56%
2027	33,672	1,420		307,635	527,736	58%
2028	33,672	1,433	32,459	310,281	544,046	57%
2029	33,672	852	156,884	187,921	434,377	43%
2030	33,672	803	44,883	177,513	443,671	40%
2031	33,672		204,251	6,934	290,263	2%
2032	33,672	38	24,195	16,449	327,118	5%
2033	33,672	76	25,752	24,445	363,072	6%
2034	33,672	215	4,517	53,815	421,754	12%
2035	33,672	377		87,864	485,493	18%
2036	33,672	411	26,911	95,036	521,692	18%
2037	33,672	331	50,930	78,109	533,850	14%

Mariner's Cove Association RA Current Assessment Funding Model VS Fully Funded Chart



The Current Assessment Funding Model is based on the <u>current</u> annual assessment, parameters, and reserve fund balance. Because it is calculated using the current annual assessment, it will give the accurate projection of how well the association is funded for the next 20 years of planned reserve expenditures.

Mariner's Cove Association RA Annual Expenditure Detail

Description	Expenditures
Replacement Year 2018	
Elastomeric Deck - Seal/Repair	3,291
Pool - Retile	57,977
Pool Furniture - Replace	5,906
Pool-Comm Salt Chlorine Generator	4,277
Signage	4,571
Stucco - Repaint	9,589
Utility Doors - Partial replace	3,515
Wading Pool - Retile	13,915
Wood Surfaces - Repaint	7,147
Total for 2018	\$110,187
Replacement Year 2019	
Elastomeric Deck - Resurface	37,580
Electronic Enrty - Replace	3,741
Total for 2019	\$41,322
Replacement Year 2020	
Kitchen - Refurbish	9,102
Pump Shut Offs - Replace	5,346
Total for 2020	\$14,448
Replacement Year 2021	
Pool/Spa Filters - Replace	2,283
Sliding Glass Doors - Partial Replacement	12,305
Vinyl Fence - Replace	13,728
Total for 2021	\$28,316
Replacement Year 2022	
Elastomeric Deck - Seal/Repair	3,562
Solar Hot Water - Replace	29,677
Total for 2022	\$33,239
Replacement Year 2023	
Appliances	444
Pole Lights - Replace	34,657
Pool-Comm Salt Chlorine Generator	4,722
Utility Doors - Partial replace	3,881
Wood Surfaces - Repaint	7,891
Total for 2023	\$51,594

Mariner's Cove Association RA Annual Expenditure Detail

Description	Expenditures
Replacement Year 2024	
Asphalt Seal/Repair	18,951
Dock - Replace	17,900
Pool Furniture - Replace	6,651
Total for 2024	\$43,502
Replacement Year 2025	
CVT Floor Replace	3,633
Pool Deck - Replace 10%	5,032
Total for 2025	\$8,664
Replacement Year 2026	
Elastomeric Deck - Seal/Repair	3,856
Kitchen - Refurbish	8,406
Total for 2026	\$12,261
No Replacement in 2027	
Replacement Year 2028	
Bathroom - Refurbish	8,677
Pool-Comm Salt Chlorine Generator	5,213
Signage	5,573
Utility Doors - Partial replace	4,285
Wood Surfaces - Repaint	8,712
Total for 2028	\$32,459
Replacement Year 2029	
Tile Roof	156,884
Total for 2029	\$156,884
Replacement Year 2030	
Chain Link Fence	26,702
Elastomeric Deck - Seal/Repair	4,173
Pool Furniture - Replace	7,490
Pump Shut Offs - Replace	6,517
Total for 2030	\$44,883
Replacement Year 2031	
Asphalt Resurface	130,077

Mariner's Cove Association RA Annual Expenditure Detail

Description	Expenditures
Replacement Year 2031 continued Asphalt Seal/Repair	21,768
Elastomeric Deck - Resurface	47,661
Electronic Enrty - Replace	4,745
Total for 2031	\$204,251
Replacement Year 2032	
Kitchen - Refurbish	11,543
Stucco - Repaint	12,652
Total for 2032	\$24,195
Replacement Year 2033	
Appliances	541
Pool-Comm Salt Chlorine Generator	5,756
Pool/Spa Filters - Replace	2,895
Tile Floor - Replace	2,211
Utility Doors - Partial replace Wood Surfaces - Repaint	4,731 9,619
-	
Total for 2033	\$25,752
Replacement Year 2034	
Elastomeric Deck - Seal/Repair	4,517
Total for 2034	\$4,517
No Replacement in 2035	
Replacement Year 2036	
Pool Furniture - Replace	8,435
Vinyl Fence - Replace	18,476
Total for 2036	\$26,911
Replacement Year 2037	
CVT Floor Replace	4,607
Pool Deck - Replace 10%	6,381
Solar Hot Water - Replace	39,942
Total for 2037	\$50,930

	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
Beginning Balance Annual Assessment Interest Earned	303,105 33,672 1,041	227,631 33,672 1,009	220,990 33,672 1,106	241,320 33,672 1,136	247,812 33,672 1,144	249,389 33,672 1,064	232,531 33,672 1,022	223,724 33,672 1,146	249,878 33,672 1,254	272,543 33,672 1,420
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	110,187 349,446 65% 227,631	41,322 349,875 63% 220,990	14,448 379,345 63% 241,320	28,316 394,976 62% 247,812	33,239 406,248 61% 249,389	51,594 399,411 58% 232,531	43,502 402,083 55% 223,724	8,664 441,813 56% 249,878	12,261 478,204 56% 272,543	527,736 58% 307,635
Description										
Appliances Asphalt Resurface						444				
Asphalt Seal/Repair BBQ - Replace	Unfunded						18,951			
Bathroom - Refurbish Block Wall _ Repair/Replace	Unfunded									
CVT Floor Replace Ceiling Fans	Unfunded							3,633		
Chain Link Fence Chain Link Fence	Unfunded									
Concrete - Special Repair Concrete Walk - Repair	Unfunded Unfunded									
Dock - Replace Elastomeric Deck - Resurface	V	37,580					17,900			
Elastomeric Deck - Seal/Repair Electronic Enrty - Replace	3,291	3,741			3,562				3,856	
Furniture - Replace Interior Surfaces - Repaint	Unfunded Unfunded									
Irrigation System Kitchen - Refurbish	Unfunded		9,102							
Kitchen - Refurbish Pole Lights - Replace						34,657			8,406	
Pool - Retile Pool Deck - Replace 10%	57,977							5,032		
Pool Furniture - Replace Pool-Comm Salt Chlorine Generator	5,906 4,277					4,722	6,651			
Pool/Spa Filters - Replace	,			2,283						

	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
Description										
Pool/Spa Pumps - Replace	Unfunded									
Pump Shut Offs - Replace			5,346							
Rock Wall - Repair	Unfunded									
Sea Wall - Repair	Unfunded									
Signage	4,571									
Sliding Glass Doors - Partial Replacement				12,305						
Solar Hot Water - Replace					29,677					
Stucco - Repaint	9,589									
Tile Floor - Replace										
Tile Roof										
Tree Trimming	Unfunded									
Utility Doors - Partial replace	3,515					3,881				
Vinyl Fence - Replace				13,728						
Wading Pool - Retile	13,915									
Wall Lights - Replace	Unfunded									
Wood Fence - Replace	Unfunded									
Wood Surfaces - Repaint	7,147					7,891				
Year Total:	110,187	41,322	14,448	28,316	33,239	51,594	43,502	8,664	12,261	

	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037
Beginning Balance Annual Assessment Interest Earned	307,635 33,672 1,433	310,281 33,672 852	187,921 33,672 803	177,513 33,672	6,934 33,672 38	16,449 33,672 76	24,445 33,672 215	53,815 33,672 377	87,864 33,672 411	95,036 33,672 331
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	32,459 544,046 57% 310,281	156,884 434,377 43% 187,921	44,883 443,671 40% 177,513	204,251 290,263 2% 6,934	24,195 327,118 5% 16,449	25,752 363,072 6% 24,445	4,517 421,754 12% 53,815	485,493 18% 87,864	26,911 521,692 18% 95,036	50,930 533,850 14% 78,109
Description	,	,	,	,	,	,	,	,	,	,
Appliances Asphalt Resurface				130,077		541				
Asphalt Seal/Repair BBQ - Replace	Unfunded			21,768						
Bathroom - Refurbish Block Wall _ Repair/Replace	8,677 Unfunded									
CVT Floor Replace Ceiling Fans	Unfunded									4,607
Chain Link Fence Chain Link Fence	Unfunded		26,702							
Concrete - Special Repair Concrete Walk - Repair	Unfunded Unfunded									
Dock - Replace Elastomeric Deck - Resurface	- J			47,661						
Elastomeric Deck - Seal/Repair Electronic Enrty - Replace			4,173	4,745			4,517			
Furniture - Replace Interior Surfaces - Repaint	Unfunded Unfunded			7,773						
Irrigation System Kitchen - Refurbish	Unfunded				11,543					
Kitchen - Refurbish Pole Lights - Replace					11,5 15					
Pool - Retile Pool Deck - Replace 10%										6,381
Pool Furniture - Replace Pool-Comm Salt Chlorine Generator	5,213		7,490			5,756			8,435	,
Pool/Spa Filters - Replace	3,213					2,895				

	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037
Description										
Pool/Spa Pumps - Replace	Unfunded									
Pump Shut Offs - Replace			6,517							
Rock Wall - Repair	Unfunded									
Sea Wall - Repair	Unfunded									
Signage	5,573									
Sliding Glass Doors - Partial Replacement										
Solar Hot Water - Replace										39,942
Stucco - Repaint					12,652					
Tile Floor - Replace						2,211				
Tile Roof		156,884								
Tree Trimming	Unfunded					4.701				
Utility Doors - Partial replace	4,285					4,731			10.476	
Vinyl Fence - Replace									18,476	
Wall Lights Parls	11									
Wall Lights - Replace	Unfunded									
Wood Fence - Replace Wood Surfaces - Repaint	Unfunded 8,712					9,619				
wood Surfaces - Repailit	0,712					9,019				
Year Total:	32,459	156,884	44,883	204,251	24,195	25,752	4,517		26,911	50,930

Pole !	Lights	- Repl	lace -	2023

Asset ID

Lighting Percent Replacement 100%
Electrical Future Cost \$31,389.62

Percent Replacement 500%

\$34,656.67

@ \$21,125.00

1

Placed in Service
Useful Life
25
Replacement Year
Remaining Life
January 1998
25
25
2023



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The 12 ft brushed aluminum light poles are in fair aged general condition. Diffusers are replaced and other minor repairs by Site Manager extending the life of the component. The anchor bolts need periodic rust treatment and sealing.

Wall Lights - Replace

Asset ID

1001 Lighting Electrical Asset Cost Percent Replacement Future Cost

100%

Placed in Service No Useful Life



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011: Operating budget component.

The (2) Coach lights adjacent to the Front door are in poor aged condition. The few other scattered lights are in varied condition. Expect to replace individual lights under the Operating budget as needed, not Reserves.

Asphalt Resurface - 2031	J	1	@ \$94,000.00
Asset ID		Asset Cost	\$100,553.48
	Parking Lot	Percent Replacement	100%
	Paving	Future Cost	\$130,076.65
Placed in Service	August 2014		
Useful Life	15		
Adjustment	2		
Replacement Year	2031		
Remaining Life	13		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Parking lot & boat storage areas. Surface is level in fair condition with some minor cracking and roughness. Asphalt curbing is dry andcrumbling and needs repair. Recommend periodic Seal coating to extend the time before major resurface project.

August 2014: Walker Moody repaired and applied two coats sealcoating for \$16,734.00.

A 1 1.	G 1/D	•	2024
Asphalt	Seal/R	enair -	7074
1 ispiiait		Cpan	404

Asset ID

Parking Lot
Paving

Paving

1 @ \$16,734.00

Asset Cost \$16,827.71

Percent Replacement 100%

Future Cost \$18,950.74

Placed in Service
Useful Life
Replacement Year
Remaining Life
September 2017
2024
6



"Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011: Parking lot & boat storage areas. The surface shows drying and some minor cracking and roughness. Curbs need repair. Seal coat is needed to extend the life of the asphalt and curbs.

August 2014: Asphalt repair and seal coat by Walker-Moody Asphalt Maintenance \$16,734.00

September 2017: SealPros repaired cracks and restriped for \$4,293.19; expensed in operating expenses.

Bathroom - Refurbish -	2028	1	@ \$6,500.00
Asset ID	1011	Asset Cost	\$7,117.95
	Interior	Percent Replacement	100%
	Building	Future Cost	\$8,676.74
Placed in Service	June 2013		
Useful Life	12		
Adjustment	3		
Replacement Year	2028		
Remaining Life	10		



New counters and fixtures were installed in 2013. 'Unit Cost' and 'Useful Life' is based on the "Full" Reserve Study by Association Reserves Hawaii LLC for the period beginning 01/1/2011.

CVT Floor Replace - 2025		1	@ \$2,895.00
Asset ID		Asset Cost	\$3,162.33
	Interior	Percent Replacement	100%
	Building	Future Cost	\$3,632.52
Placed in Service	July 2013		
Useful Life	12		
Replacement Year	2025		
Remaining Life	7		



July 2013- Tile purchased at Lowe's for \$995 was installed by Stone & Cabinet for \$1,900.00 Approx. 950 square feet, \$2,895 total.

Ceiling Fans

Asset ID

1025 Interior Building Asset Cost Percent Replacement Future Cost

100%

Placed in Service No Useful Life



(2) ceiling fans were installed in the clubhouse in 2011.

The 60" fans were purchased form The Fan Shop, Inc., \$552.62 total including fan control and installation parts. The installation by a licensed electrician was \$620.

This expense is too small to be under Reserves, include in operating expense for 'Repair & Maintenance, Building'.

Electronic Enrty - Rep	lace - 2019	1	@ \$2,950.00
Asset ID	1008	Asset Cost	\$3,668.05
	Equipment	Percent Replacement	100%
	Building	Future Cost	\$3,741.41
Placed in Service	January 2007		
Useful Life	12		
Replacement Year	2019		
Remaining Life	1		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The system is functional and in fair condition. The controller will need replacement due to wear and tear or technology advances in the future. The striker mechanism may require changing as a small expense under the operating budget between cycles.

Kitchen - Refurbish - 2	2020	1	@ \$6,500.00
Asset ID	1010	Asset Cost	\$8,748.40
	Interior	Percent Replacement	100%
	Building	Future Cost	\$9,101.84
Placed in Service	January 2003		
Useful Life	12		
Adjustment	5		
Replacement Year	2020		
Remaining Life	2		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The dated tiled counter tops are in fair condition. Cabinets are laminate in fair condition. Floor was tiled in 2013 at the same time as the main meeting room floor.

January 2014:

Countertop and sink were replaced, total cost \$6,627.67, assigned asset #1031.

This asset #1010 will be for cabinet replacement.

Kitchen - Refurbish -	2026	1	@ \$6,627.67
Asset ID	1031	Asset Cost	\$7,174.03
	Interior	Percent Replacement	100%
	Building	Future Cost	\$8,405.52
Placed in Service	January 2014		
Useful Life	12		
Replacement Year	2026		
Remaining Life	8		



<u>January 2014</u>:

Countertop and sink were replaced, total cost \$6,627.67. Floor was tiled in 2013 at the same time as the main meeting room floor. Asset #1010 will be for cabinet replacement.

Sliding Glass Doors - Partial Replacement - 2021

		1	@ \$7,500.00
Asset ID	1006	Asset Cost	\$11,595.44
	Exterior	Percent Replacement	100%
	Building	Future Cost	\$12,305.17
Placed in Service	January 1996		
Useful Life	25		
Replacement Year	2021		
Remaining Life	3		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The older doors are in fair functioning condition. Minor corrosion and wear of hardware shows extended life in a protected location. Small repairs and preventative maintenance will continue to extend the life of the doors. Window replacement is best handled under the Operating budget as a long life asset.

)	1	@ \$1,500.00
1005	Asset Cost	\$1,642.60
Interior	Percent Replacement	100%
Building	Future Cost	\$2,210.73
June 2013		
20		
2033		
15		
	Interior Building June 2013 20 2033	Interior Building Future Cost June 2013 20 2033



2013: Bathroom floors were retiled in house with tile purchased from Selective Stone for \$788.

Utility Doors - Partial re	eplace - 2018	1	@ \$3,000.00
Asset ID	1007	Asset Cost	\$3,515.01
	Exterior	Percent Replacement	100%
	Building	Future Cost	\$3,515.01
Placed in Service	January 2010		
Useful Life	5		
Replacement Year	2018		
Remaining Life	0		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

(8) wood doors total: Clubhouse has: (2) front entrance doors; (2) poolside entrance doors; (2) restroom doors; & (1) office door. The pool equipment building has 1.

The doors are in fair general condition showing normal aging. Expect to replace 2 doors on this cycle.

Interior Surfaces - Repaint

Asset ID 1024 Asset Cost
Interior Percent Replacement 100%
Paint Future Cost
Placed in Service January 2010
No Useful Life



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Interior painting is in fair scuffed condition. Painting is performed by the Site Manager under the Operating budget, not Reserves.

Stucco - Repaint - 2018		1	@ \$6,985.00
Asset ID		Asset Cost	\$9,588.55
	Exterior	Percent Replacement	100%
	Paint	Future Cost	\$9,588.55
Placed in Service	January 2002		
Useful Life	14		
Replacement Year	2018		
Remaining Life	0		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Approx 2.540 GSF

Paint is in faded fair condition with mostly full coverage. There are a few areas of stucco damage that allows water intrusion. These areas need immediate patching to protect inner structural wall.

Wood Surfaces - Repaint	- 2018	1	@ \$5,525.00
Asset ID		Asset Cost	\$7,146.79
	Exterior	Percent Replacement	100%
	Paint	Future Cost	\$7,146.79
Placed in Service	January 2005		
Useful Life	5		
Replacement Year	2018		
Remaining Life	0		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Approx 1,700 GSF, fascia, trim and eaves of buildings, and wood fence.

The paint is in poor faded condition with rusty nail heads and grime.

Elastomeric Deck - R	esurface - 2019	1	@ \$29,631.00
Asset ID	1003	Asset Cost	\$36,843.36
	Exterior	Percent Replacement	100%
	Pool	Future Cost	\$37,580.23
Placed in Service	January 2007		
Useful Life	12		
Replacement Year	2019		
Remaining Life	1		



Pool Deck was recoated by Central Pacific Specialty Contractors, Inc. April-May 2013 for \$29,631 (GET included) and included concrete repair.

Elastomeric Deck - Seal/Repair - 2018		/Repair - 2018	1	@ \$2 000 00	
'	Ziastomente Been Sea	, 110pun 2010	1	@ \$3,000.00	
	Asset ID	1002	Asset Cost	\$3,290.73	
		Exterior	Percent Replacement	100%	
		Pool	Future Cost	\$3,290.73	
	Placed in Service	May 2013			
	Useful Life	4			
	Replacement Year	2018			
	Remaining Life	0			



Pool Deck was recoated by Central Pacific Specialty Contractors, Inc. April-May 2013 for \$29,631 (GET included) and included concrete repair.


Dool Dotile 2019				
Pool - Retile - 2018			1	@ \$37,500.00
Asset ID			Asset Cost	\$57,977.19
	Pool	Pe	rcent Replacement	100%
	Pool		Future Cost	\$57,977.19
Placed in Service	January 1996			
Useful Life	20			
Replacement Year	2018			
Remaining Life	0			



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The pool is in fair aged appearance. The ocean side has sagged raising concerns about the underlying gunite foundation. Expect to retile in the future due to existing tile being no longer available.

Pool Deck - Replace 10	0% - 2025	1	@ \$4,000.00
Asset ID		Asset Cost	\$4,380.28
	Exterior	Percent Replacement	100%
	Pool	Future Cost	\$5,031.56
Placed in Service	June 2013		
Useful Life	12		
Replacement Year	2025		
Remaining Life	7		



Pool Deck was recoated by Central Pacific Specialty Contractors, Inc. April-May 2013 for \$29,631 (GET included) and included concrete repair. 'Unit Cost' and 'Useful Life' is based on the "Full" Reserve Study by Association Reserves Hawaii LLC for the period beginning 01/1/2011.

Pool-Comm Salt Chlorine Generator - 2018		1	@ \$3,923.00
Asset ID	1029	Asset Cost	\$4,276.67
	Equipment	Percent Replacement	100%
	Pool	Future Cost	\$4,276.67
Placed in Service	August 2013		
Useful Life	5		
Replacement Year	2018		
Remaining Life	0		



Purchased from All Pool & Spa August 23, 2013.

Pool/Spa Filters - Repla	ce - 2021	2	@ \$900.00
Asset ID	1014	Asset Cost	\$2,151.16
	Equipment	Percent Replacement	100%
	Pool	Future Cost	\$2,282.83
Placed in Service	January 2009		
Useful Life	12		
Replacement Year	2021		
Remaining Life	3		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

(2) Sand filters

The newer TR 140 and older TR 40 are in fair functioning condition. Pool water was crysal clear.

Pool/Spa Pumps - Replace

Asset ID 1026 Asset Cost

Equipment Percent Replacement 100% Pool Future Cost

Placed in Service No Useful Life



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The newer 1 HP pool pump and 3/4 HP wading pool pump are in fair functioning condition. Expect to rebuild por replace parts under the Operating budget, not Reserves.

enlace - 2020	2	G \$2 150 00
рисс 2020	2	@ \$2,150.00
1013	Asset Cost	\$5,138.88
Equipment	Percent Replacement	100%
Pool	Future Cost	\$5,346.49
January 2009		
10		
1		
2020		
2		
	Equipment Pool January 2009 10 1 2020	1013 Asset Cost Equipment Pool Future Cost January 2009 10 1 2020



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The newer vacuum shutoffs are reported in good functioning condition. These decices shut the pumps off if a swimmer is trapped by drain suction.

NOTICE POSTED June 2011 at Clubhouse and posted on Association's Website:

In 2008 Mariner's Cove Association had the anti-entrapment vacuum release system and the anti-entrapment pool drain covers installed on the swimming and Keiki pools to comply with Federal law.

You may have heard that some models of the anti-entrapment pool drain covers were recalled by the Consumer Product Safety Commission (CPSC).

The pool drain covers installed on the Association's pools were manufactured by New Water Solutions, Inc., model DS360M, and passed the investigation by CPSC and are not subject to the recall.

The equipment was installed by All Pool & Spa at a cost of \$3,400 total.

Wading (keiki) pool pump replaced by Oahu Pool & Spa August 2017 with anti siphon feature and more enery efficient for \$2,150.45

	C-1 II-4 W/-4 D1-	2022		
Į	Solar Hot Water - Repla	ice - 2022	1	@ \$22,050.00
	Asset ID	1009	Asset Cost	\$27,417.10
		Equipment	Percent Replacement	100%
		Pool	Future Cost	\$29,677.15
	Placed in Service	January 2007		
	Useful Life	15		
	Replacement Year	2022		
	Remaining Life	4		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Approx. 40 Panels

The HDPE 4 x 10 Ft panels are supported on a 2x4 frame and pier blocks in fair functioning condition. The system was installed in September 2007 for a reported \$20,871. The panels are covered by a 10 year warranty.

As recommeded by Association Reserves Hawaii LLC, the wood frame supports were repaired and repainted by Association personnel in 2012.

(1010		
Į	Wading Pool - Retile - 2	2018	1	@ \$9,000.00
	Asset ID	1012	Asset Cost	\$13,914.53
		Pool	Percent Replacement	100%
		Pool	Future Cost	\$13,914.53
	Placed in Service	January 1996		
	Useful Life	20		
	Replacement Year	2018		
	Remaining Life	0		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Quantity: (15) x (16) FT

The 2 FT deep pool is in fair condition. Coordinate with lager pool retile project.

Tile replacement handled in house.

D 1 D 1 2024			
Dock - Replace - 2024		1	@ \$13,300.00
Asset ID		Asset Cost	\$15,894.67
	Dock	Percent Replacement	100%
	Dock	Future Cost	\$17,899.98
Placed in Service	January 2009		
Useful Life	15		
Replacement Year	2024		
Remaining Life	6		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The composite wood deck on wood frame and plastic floats is in new good condition. Dock was installed in 2009.

Asset ID 1019 Asset Cost
CMU Percent Replacement
Fencing/Walls Future Cost

100%

Placed in Service January 2010
No Useful Life



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Approx. 4,300 LF, perimeter of boat storage

The masonary wall is in good sturdy condition. No expectation for full replacement at this time. Small repairs to mortar and cap can be expected under the operating budget. Rock wall and masonry repairs are performed by the Site Manager.

Chain Link Fence

Asset ID

1030 Chain Link Fencing/Walls June 2014 Asset Cost Percent Replacement Future Cost

100%

Placed in Service No Useful Life



CANCELLED 2015 and asset #1004 value adjusted.

June 2014:

Best Vinyl was contracted to replace 54 LF @ \$4,871.20 as follows:

8'H Galvanized Chain Link @ \$61/LF = \$3,294.00

Installation, Labor & Cement @ \$21/LF = \$1.134.00

Permit fees @ \$224.00

4.712% Tax = \$219.20

Total \$4,871.20

The 54LF replaced is assset #1030

Asset #1004 for 266 LF was adjusted as follows:

Chain link & install @ \$61/LF = \$16,226.00

Permit fees @ \$224.00

4.712% Tax = \$775.12

Total = \$17.225.12

Chain Link Fence - 2030			
Chain Link Felice - 2030		1	@ \$19,840.00
Asset ID	1004	Asset Cost	\$21,054.72
	Chain Link	Percent Replacement	100%
	Fencing/Walls	Future Cost	\$26,702.48
Placed in Service	January 2015		
Useful Life	15		
Replacement Year	2030		
Remaining Life	12		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011: Approx. 320 LF @ \$14,944 to \$19,840 (= approx. \$47/LF to \$62 LF) The fence is in fair to poor unsturdy condition. Several poles are rusted through at the base. The mesh is rusted and sagging. The intersect with the block wall has been damaged compromising the security of the boat storage.

54 LF was assigned to asset #1030 in 2014 to be replaced. But the contract was cancelled. Asset #1030 valued at \$0. and this asset revalued at \$62 LF in 2015.

D 1 1	TT 7 11	-	•
Rock '	Wall	- Rei	nair

Asset ID 1020 Asset Cost
Rock Percent Replacement 100%
Fencing/Walls Future Cost
n Service January 1968

Placed in Service No Useful Life



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Perimeter of street side parking lot, entrance to clubhouse

The low wall and halfwall of the clubhouse are in fair condition with a few missing rocks. No expectation for full replacement. Repairs are made by the Site Manager under the Operating budget, not Reserves.

a	XX7 11	D	•
Sea	Wall	- Ke	nair
DCu	v v carr	110	pan

No Useful Life

Asset ID 1021 Asset Cost
Rock Percent Replacement 100%
Fencing/Walls Future Cost
Placed in Service January 1968



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Approx 410LF, canal boundary

The rock and mortar wall is in poor eroded condition. Wave action has washed away mortar and some rock at high water locations. Small repairs to mortar and rock can be expected under the operating budget. Rock wall and masonry projects are performed by the Site Manager.

Signage - 2018		1	@ \$3,750.00
Asset ID	1015	Asset Cost	\$4,571.40
	Exterior	Percent Replacement	100%
	Fencing/Walls	Future Cost	\$4,571.40
Placed in Service	January 2008		
Useful Life	10		
Replacement Year	2018		
Remaining Life	0		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The (2) composite wood 1 x 10 Ft routered signs are in fair to good condition.

Vinyl Fence - Replace	- 2021	1	@ \$10,200.00
Asset ID		Asset Cost	\$12,936.23
	Vinyl	Percent Replacement	100%
	Fencing/Walls	Future Cost	\$13,728.04
Placed in Service	January 2006		
Useful Life	15		
Replacement Year	2021		
Remaining Life	3		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Approx. 240 LF, pool perimeter

The fence is in general fair condition.

As per the recommendation of Association Reserves Hawaii LLC, several warped 6 ft pickets were replaced by Associaiton personnel in 2012.

Wood Fence - Replace

Asset ID

Wood Fencing/Walls Asset Cost Percent Replacement Future Cost

100%

Placed in Service No Useful Life



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011: Operating budget component.

Approx 25 LF, pool entry by clubhouse office from parking lot

The fence is aged and in fair to poor condition. Deterioration at the bottom and rusty brackets and fastners were noted. Frequent repainting will extend the life of the fence. Cost to repair or replace is too small an expense for Reseves. Best to replace under the Operating budget.

Furniture - Replace

Asset ID

1023 Amenities Furniture January 1990 Asset Cost Percent Replacement Future Cost

100%

Placed in Service No Useful Life



(12) plastic 6' folding tables and approx. (60) metal folding chairs

Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

...in fair aged condition. Assume furniture items are replaced individually as needed under Operating budget.

October 2014: Forty (40) chairs were purchased to repalce the stolen chairs \$480.75; and eight (8) 6' tables were purchased \$437.36; Grand total \$918.11.

Pool Furniture - Replace	e - 2018	1	@ \$4,750.00
Asset ID		Asset Cost	\$5,905.86
	Amenities	Percent Replacement	100%
	Furniture	Future Cost	\$5,905.86
Placed in Service	January 2007		
Useful Life	6		
Replacement Year	2018		
Remaining Life	0		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The aluminum and vinyl strap furniture is in fair condition with dry fading straps and scratched and chipped frames. (15) strap chairs, (4) acrrylic top tables, and (8) strap lounges. In addition there are 2 small BBQ (samll expense) and a concrete table and bench set (unpredictable long life) that are inappropriate for Reserves.

Note:

In May 2011 (6) chaise lounges and (4) chairs were restrapped. and (1) chair completely refurbished by Mekala Powdercoat & Patio Mfg. LLC for \$682.72 total under June 2011 Operating expenses,.GL 951-5202, (R&M,Building).

Tile Roof - 2029		1	@ \$71,050.00
Asset ID		Asset Cost	\$126,176.02
	Roof	Percent Replacement	100%
	Roof	Future Cost	\$156,884.02
Placed in Service	January 1989		
Useful Life	30		
Adjustment	10		
Replacement Year	2029		
Remaining Life	11		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Approx 4060 GSF

Clubhouse and Equipment Building

Tiles appear in general fair extended life condition. Missing tiles were noted on both roofs. The tongue and groove wood ceiling of meeting room shows water stains from leaks. Reported ther are no current leaks. Small repairs are made under the Operating budget as needed. Eventually the underlayment will deteriorate to the point tile will need to be removed and reinstalled.

Appliances - 2023		1	@ \$367.00
Asset ID		Asset Cost	\$401.89
	Interior	Percent Replacement	100%
	Appliances	Future Cost	\$443.72
Placed in Service	June 2013		
Useful Life	10		
Replacement Year	2023		
Remaining Life	5		



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The older appliances are in fair used condition and are replaced as needed individually under the Operating budget. Refrigerator, microwave and range. Stove was purchased in June 2013 for \$367

Concrete - Special Repair

Asset ID 1017 Asset Cost
Exterior Percent Replacement

Exterior Percent Replacement 100%
Concrete Future Cost

Placed in Service January 1968
No Useful Life



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Boat Ramp Walls, Approx 600 GSF

The walls are in fair aged general condition. Wave action has eroded the surface in a band across the surface. Eventually a section will need replacement. Included small sidewalk repairs in this project also.

Concrete Walk - Repair

No Useful Life

Asset ID 1016 Asset Cost
Exterior Percent Replacement 100%
Concrete Future Cost
Placed in Service January 1968



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The concrete is in fair aged condition. Expect small repairs, but not full replacement. Best to include repairs with larger pool deck and/or boat ramp repairs.

BBQ - Replace

Asset ID

1018 Amenities Amenities Asset Cost Percent Replacement Future Cost

100%

Placed in Service No Useful Life



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

The concrete block construction is in poor condition. Mortar is missing in joints around the fire pit. Block shows cracks and metal parts have rusted through. Recommend rebuilding as a small one time expense under the Operating budget.

Irrigation System

Asset ID

1028 Equipment Grounds/Landscaping

January 2010

Asset Cost Percent Replacement Future Cost

100%

Placed in Service No Useful Life



All expenses for the irrigation system should be budgetd under the Operating budget, 'Repair & Maintence, Grounds' or 'Landscaping', not Reserves.

Tree Trimming

Asset ID 1027

Exterior Grounds/Landscaping

January 2010

Asset Cost Percent Replacement Future Cost

100%

Placed in Service No Useful Life



Based on "Full" Reserve Study by Association Reserves Hawaii LLC for period beginning January 01, 2011:

Tree trimming is performed under the Operating budget.